INDIANA DEPARTMENT OF NATURAL RESOURCES DIVISION OF RECLAMATION

COMPLIANCE INSPECTION REPORT

Inspector Name _ Timothy A. Corn Date of Inspecti	
Unit # 417 County Pike Date of Last Inspection 12/05/2013	
Status R Weather/Ground Conditions 30°F Overcast; Ground Part Frozen	
Inspection Type: C (P, C, PC) []	
Operation Type: X Surface Processing Exploration Underground	
Is This Inspection For Last Month? (Y/N) N	
Mines/Permits with this Unit:	
X S-354 Peabody Midwest Mining, LLC - Somerville East Mine	
INSPECTION CHECKLIST: Indicate compliance code for items checked. Items marked (S) were	
satisfactory. For any items marked (X), provide a narrative to support this	
determination. Items marked (NA) are not applicable to this inspectable unit.	
S 1. Areas Permitted, Bonded, or Unsuitable.	
S 2. Signs and Markers, Survey Corner Markers.	
NA 3. Operations, Coal Recovery, and Cessation of Operations. X 4. Backfilling and Grading, Contemporaneous Reclamation.	
X 4. Backfilling and Grading, Contemporaneous Reclamation. NA 5. Topsoil, Alternate Material, and Prime Farmland Handling.	
X 6. Revegetation/Rills and Gullies, and Slides.	
X 7. Post-Mining Land Use, Fish and Wildlife Mitigation.	
X 8. Hydrologic Balance.	
NA 9. Disposal of Coal/Non-Coal Waste, and Excess Spoil.	
NA 10. Auguring, Processing, and Steep Slopes.	
NA 11. Transportation and Support Facilities - Utility Install.	
NA 12. Casing/Sealing Exposed Underground Openings.	
NA 13. Subsidence Control Prevention.	
S 14. Liability Insurance Expires 11/01/2014	
NA 15. Bond Release Information.	
X 16. Other Permit and Site Conditions: NPDES #ING0040206; Water Monitoring	
S 17. Off-Site Impacts Noted (Y/N) N .	
(If yes, attach off-site impact form as COVER to this inspection.)	

Responsible Official & Address:	Copy Issued To:
Mr. Rich Montgomery	Not Issued on Site
UMI, LLC CC:	Peabody Midwest Mining, LLC
P.O. Box 400	7100 Eagle Crest Blvd, Ste 100
Huntingburg, IN 47542	Evansville, IN 47715
Time 1 CA	Dahar Tanuanu 15 0014
Signature: Jundly U Com	Date: January 15, 2014
Authorized Representative Division of Reclamation	
DIATRION OF VECTOMORIAN	

COMPLIANCE INSPECTION REPORT

Page _2 of _2

Permittee Peabody Midwest Mining, LLC Signature of Co. Rep. Not Completed on Site Mine Somerville East Mine Unit # 417 County Pike Date of Insp. January 15, 2014 Time 02:20 PM

COMMENTS:

- 4. Backfilling and Grading, Contemporaneous Reclamation.

 The terrace's western portion that connected Triad's pond to the final cut has been reclaimed.
- 6. Revegetation/Rills and Gullies, and Slides.
- 7. Post-Mining Land Use, Fish and Wildlife Mitigation
 - A. Land uses and vegetation of the bonded area are similarly established. The understory is stable with orchard grass, perennial rye, white clover, red clover, partridge pea and annuals in the species mix. Spraying phragmites with a chemical treatment has been completed. It will be next spring before it will be possible to find out how successful these efforts are.
 - B. The Forest and Wildlife land uses are well vegetated with a mixture of tree and shrub species including various oak sp.(red, white, swamp white, bur), hickory, bald cypress, pecan, walnut, ninebark, sycamore, tulip poplar, sweetgum, dogwood, buttonbush, river birch, maple, pine, persimmon, and others. Some volunteer species are also coming in, including cottonwood, willow, sycamore, maple and black locust. Establishment and growth continues to be good to very good throughout except in a few areas where field mice have eaten through the root collar or where deer have browsed back stem tops.
 - C. Wildlife areas are vegetated in the same manner as forest areas. Roosts instead of poisons are still encouraged to help with a natural kind of varmint control. Poisons are not compatible with fish and wildlife values and enforcement action could be at the ready if poisons or their results, especially through the food chain, become evident.
- 16. Other Permit and Site Conditions: NPDES #ING0040206; Water Monitoring
 - A. The lone remaining NPDES point and the watershed it controls have all been phase III released. Therefore, reporting should go to IDEM and not copied to the Division of Reclamation.
 - B. Repair to the stream section down gradient from the neighboring S-353 outfall has been completed with repaired slopes, riffle drop structures, self sustaining pools, etc. The repair left a small footprint where it was necessary to apply mulch on a small area at the east end of the stream section. The combination of drops and pools has been tested over the last several days and are holding up well.

Signature

Authorized Representative Division of Reclamation

Date January 15, 2014

state form 4899